

Candles and Supplies.com



HAWAIIAN LUAU CANDLES

SUPPLIES NEEDED:

Coconut Shells

Wick

Scent

Blue Candle Coloring (Blocks or Liquid)

Artificial Flowers

Glue Gun or Glue Dots

Votive Wax

Vybar 260 (optional)



Step 1

Attach the wick to the bottom of the coconut shell with either hot glue or glue dots.

Step 2

Heat the wax to 180 degrees and add the scent and coloring to the wax. Pour the wax into the coconut shell until it is within ¼" from the top of the shell so it will not overflow. (To get a ripple affect in the wax to look like water you can add more vybar to the votive wax).

Step 3

After the candle is cooled you can decorate the coconut shells with the flowers you have picked. You can glue them to the front of the shells with the hot glue or the glue dots. Make sure they are not hanging over the coconut shell near the wicking. This would be a fire hazard.